




The Kirkpatrick Group, Inc.

701 East 15th St., Suite 101. Plano, TX. 75075 USA

www.thekirkpatrickgroup.com

TWO SCREEN SHOTS FROM VIDEO SEGMENTS

Storyboard: pridepetroleum 009



This image shows the water within the Rope being forced out by the Lubricant being pressurised into the strands.

Source: Pride Petroleum



“What’s Your Breaking Point?”



This image shows the water which has been removed from within the rope, through the discharge port. Kirkpatrick allows users the ability to drain off some lubricant from the pressure collar to allow contaminants to be removed from the system.

The Drain tube is positioned so that the lubricant must first pass through the pressure chamber before being able to escape.

Source: Exxon/Mobil – Grand Ford Island.

 **STOTTS**

Australian Agent

Unit 1, 19 Balook Drive

Beresfield NSW 2322

Phone 02 4966 8020

Fax 02 4966 8302

www.stottind.com.au

